

# **XD™ FOG NOZZLE**

## **PRODUCT AWARENESS BULLETIN**

**January 2023**

### **THE ISSUE**

There has been an isolated number of occurrences where the nozzle tip can come loose and rotate more than a total of 360 degrees from wide fog/flush to straight stream positions.

### **PRODUCTS AFFECTED**

All models of Chief XD, Select-O-Matic XD, Phantom XD One-Piece Nozzles and Tips (NFPA & EN)

### **HOW TO TELL IF MY NOZZLE IS AFFECTED**

#### **Indicators**

- Tip rotates more than 360 degrees when hand force is applied
- Water may actively leak from the tip weep holes during operation
- Stream pattern may not adjust as intended when the tip is rotated

If this condition exists, it should be noticeable on your normal operational equipment testing and inspection.



### **WHAT TO DO IF MY NOZZLE IS AFFECTED**

Contact Elkhart Brass Customer Service for immediate repair.

**Phone:**  
800-346-0250  
574-295-8330

**Email:**  
eb.info@safefleet.net

**Website:**  
www.elkhartbrass.com